
KENTUCKY HISTORIC RESOURCES

(KHC 2002-1)

SHO- Listed COUNTY Pike
RESOURCE # PI-14
RELATED GROUP #

EVALUATION SHPO EVALUATION

For instruction, see the Kentucky Historic Resor	urces Survey Manual. DESTROYED
1. NAME OF RESOURCE (how determined): 0/Pauley Bridge	19. FOUNDATION:
ADDRESS/LOCATION: N. Mayo Trail Levisa Fork of Big Sandy River	20. PRIMARY WALL MATERIAL: O / NA original replacement
3. UTM REFERENCE: Quad. Name: Pikeville Date: 1992 / Zone: 17 / Accuracy: A Easting: 364260	21. ROOF CONFIGURATION/COVERING: CONFIGURATION O / NA
Northing: 4150420	22. CONDITION: P / Poor
4. OWNER/ADDRESS:	23. MODIFICATION:/ Moderate alteration
5. FIELD RECORDER/AFFILIATION:	24. NEGATIVE FILE #: 02 / 1 / 13 Write resource # on back of all prints.
H. Powell 6. DATE RECORDED: NovDec. 2002	
7. SPONSOR: KYTC Item No. 12-131.00	
8. INITIATION: 3 / Compliance US 23 Widening	
9. OTHER DOCUMENTATION/RECOGNITION:	
Survey KY Land X NR Other: Site 10 Report Reference For US 23 in Pike Co., Ky." 2003 10. ORIGINAL PRIMARY FUNCTION: 16D Bridge	
11. CURRENT PRIMARY FUNCTION: 16D Abandoned bridge	
12. CONSTRUCTION DATE: //	
13. DATE OF MAJOR MODIFICATIONS:	
14. CONSTRUCTION METHOD/MATERIAL: S / 2 / Stone piers original	COMMENTS/HISTORICAL INFORMATION:
15. DIMENSIONS: Height NA Width NA Depth NA	
16. PLAN: /	
17. STYLISTIC INFLUNCE: OO / NA : OO / NA first	
18. STYLE DEVELOPMENT: P / first/ second/ third	



KY HERITAGE COUNCIL

A CULTURAL RESOURCE SURVEY FOR US 23 IN PIKE COUNTY, KY.

Item No: 12-131.00

by

Helen C. Powell

H. Powell and Co., Inc. 509 East Maxwell St. Lexington, Kentucky 40502 (859) 233-9416

for QK4 815 West Jefferson St. Suite 300 Louisville, Ky. 40202 (502) 585-2222

Helen Powell - Principal Investigator January 2003

Lead Agency Department of Transportation

KENTUCKY HISTORIC RESOURCES INDIVIDUAL SURVEY FORM

(KHC 91-1)

DEC 19 1991

EX HERITAGE

For instructions, see the <u>Kentucky Historic Resources Survey Manual</u>.

1. NAME OF RESOURCE (how determined): 5/ PAULEY BRIDGE	16. PLAN:/ first second
2. ADDRESS/LOCATION: SPANS LEVISA FORK BILD SANDY RIVER; NORTHWEST OF US 460123 IN PIKEVILLE	third 17. STYLISTIC INFLUENCE:
3. UTM REFERENCE: Quad. Name: PIKEVILLE Date: Zone: IT Easting: 3 / 6 / 4 / 2 / 6 / 0 / Northing: 4 / 1 / 5 / 0 / 4 / 2 / 0 / Accuracy: /	
4. OWNER/ADDRESS: CITY OF PIKEVILLE P.O. BOX 363 PIKEVILLE KY. 41501	19. FOUNDATION: TYPE MATERIAL / original
5. FIELD RECORDER/AFFILIATION: H. POWELL, CONSULTANT	/replacement
6. DATE RECORDED: 12/1/91	20. PRIMARY WALL MATERIAL: original replacement
7. SPONSOR: PIKEVILLE BEVIEW BOARD	21. ROOF CONFIGURATION/COVERING:
8. INITIATION: 2/	CONFIGURATION COVERING
9. OTHER DOCUMENTATION/RECOGNITION: Determine Survey HABS/HAER Local Land NR R&C NHL Other:	22. CONDITION: 4/ GEST 23. MODIFICATION: 1/ LUTTUE AMERA 24. NEGATIVE FILE #: //
O. ORIGINAL PRIMARY FUNCTION: 1/6/F/ VEHICULAL SOUNDED BELDGE	Write resource # on back of all prints.
1. CURRENT PRIMARY FUNCTION: 1/6/F/ VEHICULAR SWINGING BRIDGE	PHOTO ATTACHED TO BACK SIDE OF
2. CONSTRUCTION DATE: 3 / M25 - 49 estimated documented	SHEET
3. DATE OF MAJOR MODIFICATIONS (specify): 2/ PLANK SIDEWALL ADDRED	
4. CONSTRUCTION METHOD/MATERIAL: 5/2/ STONE TOWERS original X/X/ WIRE CABLES subsequent	
15. DIMENSIONS: Height Width 10.8 Depth 370 SF&L	

26. SITE PLAN (Complete if #25 was answered).

